

During the weekend of June 2 & 3, 2012, there was a major washout from the East Ski area parking lot at Shawnee Peak. A significant amount of sand, silt and gravel made its way into Moose Pond. Additional phosphorous was added to the lake not only from this washout but by other runoff from the Mountain Road area. The photos below show some of the damage done to the shoulders of Mountain Road and the aggregate that was dumped into Moose Pond. Moose Pond Association is working with Lakes Environmental Association (LEA), the Cumberland County Soil and Water Conservation District (CCSWCD), the Town of Bridgton and Shawnee Peak to provide better solutions to the runoff problems and to prevent occurrences like this from happening in the future.






Shawnee Peak East Area Drive



Where some of the gravel went from the drive (left side of drive)



Mountain Road to left of Drive





Mountain Road



Mountain Road



Mountain Road from 366 End